


I31A Encounter Overview



Note: DSS-63 is off-line for an extended period of X-Band Uplink upgrades, and is unavailable for use.

Two Bus Reset PORs occurred during the encounter time period, both of which were properly handled by the on-board recovery routine.

The times were: 01-217/22:21-22:47 SCET (exact time is indeterminate) and 01-218/11:12:09 SCET.

BMcL/SST
08/20/01