


I33A Encounter Period Overview



Note: Sequence activities were canceled at 02-017/13:41:09.933 by safing apparently caused by a despun bus reset that was not caught by the patch. Another despun bus reset occurred at 02-018/02:44:56.400 that was correctly handled by the patch.

SAB/BMcL/SST
1/24/02